

99 P 4 1 1 0

1/1




Fig. 1




Fig. 2

Reference symbols

- 1 Shaft
- 2 Bearing
- 3 Frame support
- 4 Tool rest
- 5 Leadscrew
- 6 Ring gear
- 7 Pinion
- 8 Main motor
- 9 Tool
- 10 Support
- 11 Pinion
- 12 Ring gear
- 13 Rest motor
- 14 Toothed belt
- 15 Slip rings

- 17 Pinion